


Manufacturer Details

PulseLarsen Antennas W5012
IP65 868MHz/915MHz 179mm Radome
Return loss: -8dB




Conclusion

Fail. 868MHz only.

Manufacturer Details

Laird 0600-00028
900MHz, 2.5dBi, right Angle 1/2 wave whip
VSWR: <2.0:1 (equiv. S11 is -9.5dB)




Conclusion

Pass up to ~930MHz
~890MHz centre frequency.

Manufacturer Details

MultiTech AN868-915A-10HRA
868-915MHz, 3.0dBi, 8"



Conclusion

Borderline. Better at 868MHz.

Manufacturer Details

Molex WM9669-ND
868/915MHz, 1.4dBi, 79x10mm, standalone
S11: < -6dB




Conclusion

Fail. Even worse at 868MHz.
Double centre @ 960MHz & 1000MHz

Manufacturer Details

Anaren 66089-0906
U.FL 915MHz, 3dBi, 82mm
6mm "standard" strain relief



Conclusion

Excellent!

Manufacturer Details

Anaren 66089-0930
U.FL 915MHz, 3dBi, 82mm
30mm "extended" strain relief



Conclusion

Terrible! Centre frequency @ 700MHz??